

# Action taken on the Water supply issues reported

DINAMALAR -01/02/2026



250mm CI pipe leak was rectified and water supply effected on 31.01.2026 under KAYATHAR CWSS

# Action taken on the Water supply issues reported

DINAMALAR -02/02/2026

## குழாய் உடைந்து விணாகும் குடிநீர்


உடுமலை, பிப். 2: கணியூர்-காரத்தொழுவு சாலையில் திருமுர்த்தி கூட்டு குடிநீர் திட்ட இரும்பு குழாய் செல்கிறது. இதன்மூலம் ஏராளமான கிராமங்கள் குடிநீர் வசதி பெறுகின்றன. துங்காவியில் பம்பு ஹவுஸ் உள்ளது.



இதில், வஞ்சிபுரம் அருகே குழாயில் ஓட்டை விழுந்து தண்ணீர் பீய்ச்சியடித்து விணாகிறது. பல வாரங்களாக இந்த நிலைமை உள்ளது. குடிநீர் விணாகி காட்டுப்பகுதியில் வழிந்தோடுகிறது. இதன் காரணமாக சில கிராமங்களுக்கு குடிநீர் வருவதில் சிக்கல் ஏற்பட்டுள்ளது. இதுபற்றி அப்பகுதி மக்கள் அதிகாரிகளிடம் தெரிவித்தும் எந்த நடவடிக்கையும் எடுக்கவில்லை. எனவே, உடனடியாக குழாய் உடைப்பை

▶ கணியூர்- காரத்தொழுவு சாலை வஞ்சிபுரம் அருகே திருமுர்த்தி கூட்டுக்குடிநீர் திட்ட குழாயில் உடைப்பு ஏற்பட்டு தண்ணீர் விணாகிறது.

சரி செய்ய வேண்டும் என பொதுமக்கள் கோரிக்கை விடுத்துள்ளனர்.



Madathukulam, Tamil Nadu, India  
117, Anna Nagar, Karatholuvu Kaniyur To Karatholuvu, Road,  
Madathukulam, Tamil Nadu 642203, India  
Lat 10.618954° Long 77.374255°  
Tuesday, 03/02/2026 11:17 AM GMT +05:30

150mm MS scour valve leak was rectified and water supply effected on 03.02.2026 under Madathukulam in Tiruppur District

# Action taken on the Water supply issues reported


DINAMALAR -09/02/2026



140mm PVC pipe leak was rectified and water supply effected on 09.02.2026 under DINDIGUL CWSS

# Action taken on the Water supply issues reported


DINAMALAR -09/02/2026



140mm HDPE pipe leak was rectified and water supply effected on 09.02.2026 under DINDIGUL CWSS

# Action taken on the Water supply issues reported

DINATHANTHI -11/02/2026



63mm PVC pipe leak was rectified and water supply effected on 12.02.2026 under CWSS to 378 (221+157) habitations in pollachi North ,Pollachi South and kinathukadavu unions in coimbatore District

# Action taken on the Water supply issues reported

DINATHANTHI -13/02/2026



Pipe leak was rectified and water supply effected on 13.02.2026 under CWSS to 547 Habitations in Namakkal district

# Action taken on the Water supply issues reported

DINAMALAR -17/02/2026



500mm PSC pipe leak was rectified and water supply effected on 18.02.2026 under CWSS to 378 (221+157)habitations in pollachi North ,Pollachi South and kinathukadavu unions in coimbatore District

# Action taken on the Water supply issues reported

DINAMALAR -21/02/2026



90mm PVC pipe leak was rectified and water supply effected on 20.02.2026 under CWSS to Gundalapatti & 36 other habitations IN Dharmapuri district

# Action taken on the Water supply issues reported

DINAKARAN -22/02/2026



250mm PSC pipe leak was rectified and water supply effected on 18.02.2026 under CWSS to 378 (221+157)habitations in pollachi North ,Pollachi South and kinathukadavu unions in coimbatore District

# Action taken on the Water supply issues reported

DINAKARAN -22/02/2026



Damaged pipeline rectified and water supply effected on under CWSS to 547 Habitations in Namakkal District

# Action taken on the Water supply issues reported

DINAKARAN -25/02/2026

**ஓகேனக்கல் கூட்டு குடிநீர் திட்ட குழாய் உடைந்து வீணாக வெளியேறிய தண்ணீர் 10 அடி உயரத்திற்கு பீய்ச்சி அடித்ததால் பரபரப்பு**

தல் லம்பள்ளி, (பிப்.25) தரம்புரி மாவட்டம் தல் லம்பள்ளி அடுத்தள்ள புறவடை ஊர்ஷன் பகுதி வழியாக தேசிய நெடுஞ் சாலை செல்கிறது. இந்த சாலையில் இருபுறமும் விரிவாக்கப் பணிகள் நடைபெற்று வருகிறது. இதனால் புறவடை ஊர்ஷன் பகுதி யோரம் சாலைவழிப்புறத் தும் பணி நடைபெற்று வருகிறது. இந்நிலையில் தேற்று மாலை அவ்வழி யாக சென்ற ஓகேனக்கல் கூட்டு குடிநீர் திட்ட பிரதான குழாய், உடைந்து தண்ணீர் வெளியேறத் தொடங்கியது. சித்தூரேத் தில் தண்ணீர் மேகம் அதிக மானதால், சுமார் 10 அடி உயரத்துக்கு மேல் தண்ணீர் பீய்ச்சி அடித்து, இதனால் பல்லாரிர்ம் விட்டர் ஓகே னக்கல் குடிநீர் வீணாக வெளியேறியது.

அதேபோல் கெவ்வலர் புரம் பகுதியில் ஓகேனக்கல் கூட்டு குடிநீர் குழாயில் பிரதான குழாயில் உடைப்பு ஏற்பட்டு, கடந்த 2 நாட்க ளாக தண்ணீர் வீணாக வெளியேறியது. அதன் பிறகு உடைந்த குழாயை சீரமைத்தவர்கள், தோள் டிய குழியை அப்படி மே விட்டுவிட்டு சென்றனர். இதனால் ஓரடிநேரங்களில் அந்த வழியாக செல்லும் வாகன ஓட்டிகள் விபத்தில் சிக்கும் ஆபாயம் ஏற்பட்டுள்

எது ஓகேனக்கல் கூட்டு குடிநீர் திட்ட குழாய் உடைந்த அன்றே சம்பந்தப்பட்ட அதிகாரிகள் விவரத்துறவு டி க்கை எடுத்து, உடைந்த குழாயை சீரமைத்து இருத் தால் பல்லாரிர்ம் விட்டர் தண்ணீர் வீணாகுவது தடுக்கப்பட்டு இருக்கும் ஆனால் 2 அல்லது 3 நாட் கள் ஆகிற்றுதான், உடைந்த குழாயை சீரமைக்கின்றனர் என பொதுமக்கள் குறும் சாட்டுகின்றனர்.




**செங்கமங்கலம் - GAIL உடைப்பு - 110 mm - HDPE PND - உடைப்பு சரி செய்து உட்கட்டி**




உதவி நிர்வாக இயக்குநர் (பி.ஓ.ஓ.பி.) திட்ட - ஸ்தலத்தின் உ.பி. மேன்.பி.ம். துறாவளி 25-02-2026 - ஓகேனக்கல் - ஓகேனக்கல் - ஓகேனக்கல்




25-02-2026 - ஓகேனக்கல் - GAIL உடைப்பு - 110 mm - HDPE PND - உடைப்பு சரி செய்து உட்கட்டி

110mm HDPE & 140mm HDPE pipe leak were rectified and water supply effected under Hogenakkal Water Supply and Fluorosis Mitigation Project .

# Action taken on the Water supply issues reported

DINAKARAN -27/02/2026



140mm HDPE pipe leak were rectified and water supply effected on 27.02.2026 under Hogenakkal Water Supply and Fluorosis Mitigation Project .

# Action taken on the Water supply issues reported

DINATHANTHI -28/02/2026



200 mm DI pipeline was rectified and water supply effected on 28.02.2026 under CWSS to Kambalapatti and 24 Rural Habitations in Anamalai and Pollachi South unions of Coimbatore district